

SIMONDS SCHOOL

AHERA SIGNATURE TABLES

**School Administrative Unit No. 65-
Kearsarge Regional School District
Simonds Elementary School
Warner, New Hampshire**

Warner, New Hampshire						
1870's Wing Room #	Sample Description	EPA Category	Quantity	EPA Assess- ment	Response Action	Date: 6-Month Insp. Changes Y/N
Staff Bathroom	9" x 9" Black and Gray Floor Tiles/Mastic (Under 12" x 12" tiles)	Misc.	50 ft²	5	1	N
Supply Closet			200 ft²			
Room 12, Nurse's Office			280 ft²			
Room 18		Abated By OneSource Environmental in Summer 2019				
Room 19						
Room 20						
Room 21						

Note: ft² = Square feet, If yes, note any changes for 6-Month re-inspection.

Inspector: Stephen McPherson #A1000204

Date: July 2021

Simonds Elementary School - AHERA Reinspection, Page 1

**School Administrative Unit No. 65-
Kearsarge Regional School District
Simonds Elementary School
Warner, New Hampshire**

Center Wing Room #	Sample Description	EPA Category	Quantity	EPA Assessment	Response Action	Date: 6-Month Insp. Changes Y/N
Room 9, Staff Room	9" x 9" Gray Floor Tile/Mastic (Under Carpet)	Abated By OneSource Environmental in Summer 2019				
Room 11, Principal's Office		Abated By OneSource Environmental in Summer 2019				
Room 22, Copy Room inside Main Office						
Room 23 Main Office						
Room 29 (Was listed as 25)	9" x 9" Gray Floor Tile/Mastic (Under Carpet and 12" x 12" Floor Tiles)	Abated by OneSource Environmental July 2018				
Room 27						
Room 26 (Was listed as 28)	9" x 9" Gray Floor Tile/Mastic (Under Carpet)					
Room 30 Staff Work Room	9" x 9" Gray Floor Tile/Mastic					

Note: ft² = Square feet, if yes, note any changes for 6-Month re-inspection

Inspector: Stephen McPherson #A1000204

Date: July 2021

The EPA Assessment Codes identified in the Table above are as follows:

1. Damaged or significantly damaged thermal system insulation Asbestos-Containing Materials (ACM).
2. Damaged friable surfacing ACM.
3. Significantly damaged friable surfacing ACM.
4. Damaged or significantly damaged friable miscellaneous ACM.
5. Asbestos-Containing Building Materials (ACBM) with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

The Response Action Codes identified in the Table above are as follows:

1. Monitor identified material under the Operations and Maintenance Program.
2. Repair, encapsulate or enclose identified material, decontaminate immediate area, then monitor under the Operations and Maintenance Program.
3. Remove identified material, decontaminate immediate area. Remove material from Table above.

Inspector: Stephen McPherson #A1000204

Date: July 2021

Simonds Elementary School - AHERA Reinspection, Page 3